



No DX1300365

Test Report

Name of sample XLPE Insulated 0.6/1(1.2) kV Service Cables

Specifications X-90 0.6/1kV 4×16mm²

Inspected unit Nanyang Cable (Tianjin) Co., Ltd.

Test purpose Type Test




Guangdong Testing Institute Of Product Quality Supervision
(GQI)

Guangdong Testing Institute of Product Quality Supervision

TEST REPORT

No DX1300365

P.1/5

Name of sample	XLPE Insulated 0.6/1(1.2) kV Service Cables	Type	X-90 0.6/1kV 4×16mm ²
		Trade mark	NAN
Inspected unit	Nanyang Cable (Tianjin) Co., Ltd.	Test purpose	Type Test
Produced by	Nanyang Cable (Tianjin) Co., Ltd.	Class of sample	—
Place of sampling	—	Date of sampling (receiving)	2013.02.05
Quantity of sampling	30 m	Person of sampling (sending)	LIN Liantao
Basic quantity of sampling	—	No. of sample tested or produced date	—
Based on	AS/NZS 4026:2008 Electric cables —For underground residential distribution systems	Tested items	37 items
Remarks	37 items were checked according to AS/NZS 4026:2008, the test results met the technical requirements based on .  Date of issue 2013-03-21		
Notes	Bill of testing plan: YDD13/0646.		

Approved by:

Checked by :

Tested by :